





Negative bias (laser)

Do not use (wire-bonding)


NS - twins	V1
Alpes Lasers SA	



 Negative bias (laser)

 Do not use (wire-bonding)

HP-GS epi-dn	V1
Alpes Lasers SA	



 Positive bias (laser)


 Thermistor zone

 Negative bias (laser)

 Thermistor contacts

 Do not use (wire-bonding)

AN3U	V1
Alpes Lasers SA	



 Positive bias (laser)


 Thermistor zone

 Negative bias (laser)

 Thermistor contacts

 Do not use (wire-bonding)

AN3D	V1
Alpes Lasers SA	



 Negative bias (laser)

 Do not use (wire-bonding)

AN-NSP	V1
Alpes Lasers SA	